Dart Aerospace Ltd. Kim Johnston Liser **Process Sheet Drawing Name** : STEP WELDMENT : CU-DAR001 Dart Helicopters Services Customer Job Number : 32382A **Estimate Number** : 10176 : D2563 Part Number P.O. Number :NIA : D2563 REV C S.O. No. : NA **Drawing Number** : 5/16/2007 This Issue : N/A : NC Project Number Prsht Rev. First Issue Type : LARGE FAB ASSY **Drawing Revision** : NW : 30508A Material Previous Run : 5/30/2007 10 Um: Each **Due Date** Written By Checked & Approved By : Est Rev; G 02.07.31 Re-format Location RF Comment **Additional Product** Job Number: Machine Or Operation: Description: Seq. #: 1.0 D2244116 Step Extrusion Comment: Qty.: 10.0000 Each(s) 1.0000 Each(s)/Unit Total: Pick: Step Extrusion D2244 10 Batch: D267334 End Plate 2.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 20.0000 Each(s) Pick: Description Qtv Part No. Batch R25396 D2673-34 End Cap D2561 Lug Plate 3.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 20.0000 Each(s) Pick: Description Qty Part No. 2 D2561 Lug Plate 4.0 D2564 Mounting Angle Comment: Qty.: 2.0000 Each(s)/Unit Total: 20.0000 Each(s) Pick: Part No. Description Batch 330464 Qty D2564 Mounting Angle

Dart Aerospace Ltd

W/O:				WORK ORDER	CHANGES					
DATE	STEP		PROCEDU	IRE CHANGE	·	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector
						<u> </u>				
		· .		•						
					30°					
Part No) <u>.</u>	P	AR #: Fa	ault Category:	NC	R: Yes	No DQ	Δ: .	Date:	1

Part No: _	 PAR #:	Fault Category:	NCR: Yes	No	DQA: _	·	Date: _	
			QA: N	I/C C	losed:		Date:	

NCR:		W	ORK OR	DER NON-CONFORMANCE	E (NCR)			
		Description of NC		Corrective Action Section B		Verification	Approval	Approval QC Inspector
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	
				`				
						l		
				and the same of th				
			•					
	<u> </u>							
				man man the state of the state				
				N >				
-								

NOTE: Date & initial all entries

Date: Wednesday, 5/16/2007 8:14:38 AM User: Kim Johnston **Process Sheet** Drawing Name: STEP WELDMENT Customer: CU-DAR001 Dart Helicopters Services Job Number: 32382A Part Number: D2563 Job Number: Seq. #: Machine Or Operation: Description: LARGE FAB 1 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 a.n Sh 02.06.11 1-Cut D2244 to 89.70" at 34° as per Dwg D2563 2-Deburr ends 3-Weld (1 End CAP, LUG PLATES & MOUNTING ANGLE as per Dwg D2563 using DT 8343 Batch: M102756 4-Grind QC5/9 6.0 Comment: WELD INSPECTION 7.0 HAND FINISHING HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 8.0 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 9.0 LARGE FABRICATION RESOURCE Comment: LARGE FABRICATION RESOURCE 1 1-Inspect for foreign object per QSI 024 2-Weld Remainig End as per Dwg D2563 using DT 8343 Batch: <u>M/04305</u> A/R AL ROD 10 3-Grind QC9 10.0 VISUAL WELDING INSPECTION Comment: VISUAL WELDING INSPECTION

Dart Aerospace Ltd

W /O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
			"se		•					
			•							
		3								
		!								

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA: 💭	Date: <u>07/6/d/5</u>
			QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification Section C	Approval Chief Eng	Approval QC Inspector			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date						
						,					
					7						
				i							
				·							

NOTE: Date & initial all entries

Date: Wednesday, 5/16/2007 8:14:38 AM User: Kim Johnston **Process Sheet** Drawing Name: STEP WELDMENT Customer: CU-DAR001 Dart Helicopters Services Job Number: 32382A Part Number: D2563 Job Number: Seq. #: Description: **Machine Or Operation:** INSPECT WORK TO CURRENT STEP QC5 11.0 Comment: INSPECT WORK TO CURRENT &TEP POWDER COATING 12.0 POWDER COATING 1104144 Comment: POWDER COATING Touch up Alodine then Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 HAND FINISHING1 HAND FINISHING RESOURCE #1 13.0 Comment: HAND FINISHING RESOURCE #1 Wing Walk as per Dwg D2563 and QSI 005 4.4 14.0 QC3 INSPECT POWDER COAT/CHEMICAL Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 15.0 QC21 Comment: FINAL INSPECTION/W/O RELEASE U 87.06.15 Job Completion

Dart Aerospace Ltd

W/©:		WORK ORDER CHANGES								
DATE STEP		PROCEDURE CHANGE	By Date		Approval Chief Eng / Prod Mgr	Approva QC Inspector				
		Astronomic				•				
			13,	,						
		•								
					*					

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
•			QA: N/C C	losed:	Date:

NCR:	i	WORK ORDER NON-CONFORMANCE (NCR)										
	T	Description of NC		Corrective Action Section B		Verification	Approval	A				
DATE	STEP	Section A	Initial Action Description Chief Eng Chief Eng			Sign & Section C		Approval QC Inspector				
		· !	-									
			-		,			,				
				·			4					
			-									
		·										
			:									
								,				
				·								
				•								

NOTE: Date & initial all entries

